

Release Notes – Firmware v3.1.3.1402

1. Overview

This document summarizes the major updates for the AP firmware from v3.1.3.1317 to v3.1.3.1402. The firmware update is applicable to the below products.

AP Product Series:	H/W version
CX200	All

2. What's New in v3.1.3.1402

2.1. New Features

1. Support remote factory reset by using the reset button of PoE injector.

2.2. Bug Fixes

1. Ethernet LED not lighting up when there is no data activity on it. It should give steady green light by design.