



802.11ac Wave 1 AP Products or Before



Important Note :

- # For A8n series running firmware versions earlier than v1.2.6.1701, it is recommended to back up the configuration and reset to factory default first and then perform the firmware update. The backup file is used to recover the configuration after the update.
- * For A2 or C1n/C1an series running firmware versions earlier than v1.2.4.x (x<1821), it is recommended to reboot it via WebUI first and then perform the firmware update.
- * For C1n running firmware v3.2.0.14xx, it is recommended to reduce the number of WLANs down to four (4) or below. After save and apply, reboot the C1n and then proceed with the firmware update.

802.11ac Wave 2 AP Products



802.11ax (Wi-Fi 6) AP Products

